



AXLE SPINDLE NUT SPECIFICATIONS

Sorted by Stamp Number

Stamp #	Thread Size	EMPI #
1 or 1011	M22 X 1.5	87-1011
2 or 1012	M22 X 1.5	87-1012
3 or 1013	M24 X 1.5	87-1013
4 or 1191	M22 X 1.5	87-1191
5 or 1531	M22 X 1.0	87-1531
6 or 1532	M24 X 1.5	87-1532
7 or 1161	M22 X 1.5	87-1161
9 or 1291	M20 X 1.5	87-1291
10 or 1461	M22 X 1.5	87-1461
11 or 1462	M22 X 1.0	87-1462
12 or 1411	M20 X 1.0	87-1411
13 or 1412	M20 X 1.0	87-1412
14 or 1311	M18 X 1.5	87-1311
15 or 1711	M19 X 1.5	87-1711
16 or 1131	M20 X 1.5	87-1131
17 or 1132	M24 X 2.0	87-1132
18 or 1641	M18 X 1.5	87-1641
19 or 1642	M20 X 1.5	87-1642
20 or 1643	M24 X 1.5	87-1643
22 or 1071	M20 X 1.5	87-1071
23 or 1072	M22 X 1.5	87-1072
24 or 1463	M16 X 1.5	87-1463
25 or 1464	M16 X 1.5	87-1464
26 or 1715	M20 X 1.5	87-1715
27 or 1712	M22 X 1.5	87-1712
28 or 1720	M26 X 1.5	87-1720
29 or 1721	M27 X 2.0	87-1721
30 or 1722	M20 X 1.5	87-1722
31 or 1725	M24 X 1.5	87-1725
32 or 1726	M24 X 1.5	87-1726
33 or 1728	M22 X 1.5	87-1728
34 or 1729	M28 X 1.5	87-1729
36 or 1723	M22 X 1.5	87-1723
37 or 1730	M24 X 1.5	87-1730
1731	M22 X 1.5	87-1731
1732	M22 X 1.5	87-1732
1734	M20 X 1.5	87-1734
1736	M22 X 1.5	87-1736
1737	M27 X 1.5	87-1737
1738	M24 X 2.0	87-1738
1739	M22 X 1.5	87-1739
1740	M20 X 1.5	87-1740
1743	M22 X 1.5	87-1743
1744	M22 X 1.5	87-1744
1745	M24 X 2.0	87-1745
1746	M21 X 1.5	87-1746
1748	M10 X 1.5	87-1748
1749	M24 X 1.5	87-1749
Bolt	M14 X 1.5	87-1724
Bolt	M16 X 1.5	87-1727

Sorted by Thread Size

Thread Size	EMPI #	Stamp #
M10 X 1.5	87-1748	1748
M14 X 1.5	87-1724	Bolt
M16 X 1.5	87-1463	24 or 1463
M16 X 1.5	87-1464	25 or 1464
M16 X 1.5	87-1727	Bolt
M18 X 1.5	87-1311	14 or 1311
M18 X 1.5	87-1641	18 or 1641
M19 X 1.5	87-1711	15 or 1711
M20 X 1.0	87-1411	12 or 1411
M20 X 1.0	87-1412	13 or 1412
M20 X 1.5	87-1071	22 or 1071
M20 X 1.5	87-1131	16 or 1131
M20 X 1.5	87-1291	9 or 1291
M20 X 1.5	87-1642	19 or 1642
M20 X 1.5	87-1715	26 or 1715
M20 X 1.5	87-1722	30 or 1722
M20 X 1.5	87-1734	1734
M20 X 1.5	87-1740	1740
M22 X 1.0	87-1462	11 or 1462
M22 X 1.0	87-1531	5 or 1531
M22 X 1.5	87-1011	1 or 1011
M22 X 1.5	87-1012	2 or 1012
M22 X 1.5	87-1072	23 or 1072
M22 X 1.5	87-1161	7 or 1161
M22 X 1.5	87-1191	4 or 1191
M22 X 1.5	87-1461	10 or 1461
M22 X 1.5	87-1712	27 or 1712
M22 X 1.5	87-1723	36 or 1723
M22 X 1.5	87-1728	33 or 1728
M22 X 1.5	87-1731	1731
M22 X 1.5	87-1732	1732
M22 X 1.5	87-1736	1736
M22 X 1.5	87-1739	1739
M22 X 1.5	87-1743	1743
M22 X 1.5	87-1744	1744
M24 X 1.5	87-1013	3 or 1013
M24 X 1.5	87-1532	6 or 1532
M24 X 1.5	87-1643	20 or 1643
M24 X 1.5	87-1725	31 or 1725
M24 X 1.5	87-1726	32 or 1726
M24 X 1.5	87-1730	37 or 1730
M24 X 1.5	87-1746	1746
M24 X 1.5	87-1749	1749
M24 X 2.0	87-1132	17 or 1132
M24 X 2.0	87-1738	1738
M24 X 2.0	87-1745	1745
M26 X 1.5	87-1720	28 or 1720
M27 X 1.5	87-1737	1737
M27 X 2.0	87-1721	29 or 1721
M28 X 1.5	87-1729	34 or 1729

Spindle Nuts